

Notes on the correct use of the headsets!

Warning! This headset can cause the aircraft communication equipment (ie: intercom and radios) to function differently than intended if the latter does not support the operation of the headset. This warning applies for the following models:

Product Name	Part No.	Cat. No.
HMEC 25-BA	025-230-215	004438
HMEC 25-KAL	025-230-615	004935
HMEC 25-KAP	025-230-315	004567
HMEC 25-KAP-1	025-230-316	004568
HMEC 25-KAP-2	025-230-715	005307
HMEC 25-KAP-2 DIAMOND	025-230-715	500528
HMEC 45-KAP	045-230-315	004570
HMDC 25-BAA		004463
HMEC 302	300-231-715	005306
HMEC 352	300-231-7150	500567
HMEC 46-KP	046-35-999-3111	500475
HMEC 46-V-KP	046-35-999-3161	500476

The above models obtain their operating DC supply voltage via the tip (pin 1) of the microphone plug (PJ 068 or equivalent). The communication equipment must provide the DC supply at this contact in order to activate the NoiseGard™ function of the headset. However, some aircraft communication systems use this contact for the PTT (push to transmit), or other, function. For this reason, inserting the microphone plug can cause the PTT function to be partly or completely triggered unintentionally.

If you have any questions in this connection, please contact the aircraft manufacturer or an approved avionics service company.