



## TeamConnect Ceiling Medium

Ceiling microphone array

### Firmware Update

- The TeamConnect Ceiling Medium firmware update requires the Sennheiser Control Cockpit software: [www.sennheiser.com/control-cockpit-software](http://www.sennheiser.com/control-cockpit-software)

### Firmware version 1.7.0 - Release Date 2026-02-23

For conformity, consistency and compatibility reasons, we strongly recommend upgrading the system to the new release.

- Upgraded Operating System to the latest patch level
- Upgraded OpenSSH module to v.10.2p1
- Implemented SSCv2 interface version 1.9
- Improved the beam position angle information regarding accuracy and stability
- Improved the beam position angle information stability during far-end-activity and speech pauses

### Previous Releases

#### Firmware version 1.6.0 - Release Date 2025-08-12

- Upgraded Operating System to the latest patch level
- Upgraded OpenSSH module to v9.9p2
- Implemented SSC interface version to 1.8
- Added SSC endpoint to enable and disable the low-cut filter (60Hz)

#### Firmware version 1.5.4 - Release Date 2025-01-31

- Updated operating system with patched modules
- Adapted low-cut filter to reduce low-frequency noise pickup

#### Firmware version 1.5.2 - Release Date 2024-10-23

- OpenSSH 9.8p1 to fix CVE-2024-6387
- Fixed renewal of TLS certificate
- Reset Intelligent Noise Control parameters with audio reset

#### Firmware version 1.5.0 - Release Date 2024-06-04

- New Intelligent Noise Control, which detects and suppresses unwanted constant background noise in noisy environments for enhanced voice tracking
- Updated operating system with patched modules
- Providing open source licenses via Sennheiser Control Cockpit claiming process
- Using MAC based link local IPv4 address instead of a randomly generated one
- Allowing LED identification for the API user



## **Firmware version 1.2.7 - Release Date 2023-10-23**

- Fix broken firmware update for devices which never received an update before

## **Firmware version 1.2.5 - Release Date 2023-09-19**

- The internal operating system has been updated.
- The internal handling of continuous beam angle data polling has been fixed.
- In case of Dante port has no IPv4 address, the address is displayed as '0.0.0.0'.
- The property 'maxLength' has been removed from timezone in '/api/device/time'.
- The default setting of '/api/audio/outputs/analog' has been fixed to 'LocalOutput'.
- The response on invalid strings for device name, location and position are returned as '400' now.
- An active termination is applied to all subscriptions in case of IP address change, factory reset and reboot.

## **Firmware version 1.2.3 - Release Date 2023-06-29**

Initial Customer Release v.1.2.3