



## TeamConnect Ceiling 2

Ceiling microphone array

### Firmware version 1.3.4 - Release Date 2019-08-30

For conformity, consistency and compatibility reasons, we strongly recommend upgrading the system to the new release.

#### Features

- Configuration of horizontal exclusion zones
- New Dante output level control (0dB to +24dB)
- Dante output gain increased by +12dB (default)
- Supports usage of external AEC Reference channel on Dante Input (requires TCC2 Dante firmware  $\geq$  v1.1.0)

#### Firmware Update

- The TeamConnect Ceiling 2 firmware update requires the Sennheiser Control Cockpit software: [www.sennheiser.com/control-cockpit-software](http://www.sennheiser.com/control-cockpit-software)

### Previous Releases

#### Firmware version 1.2.1

- Dynamic vertical exclusion zones
- Orientation offset feature added

#### Firmware version 1.1.0

- LED colours for mic on, muted and custom state selectable
- 10° static vertical exclusion zone
- Audio performance for suspended installation improved for higher frequencies