


Advanced features of the LSP 500 PRO Firmware Update Version 1.6.1 and the iPad App 1.6

With the new features developed for the hassle-free wireless PA system LSP 500 PRO, the usability of this game-changing system has been further enhanced.


The new firmware 1.6.1 offers many improvements and new features regarding WLAN-/ Bluetooth connectivity and the built-in USB player. Especially the performance of the wireless control has been improved. The new firmware is available for download on the Sennheiser LSP 500 PRO product web page.

iPad App 1.6

The LSP 500 PRO iPad app has been significantly revised resulting in a more stable connectivity and a better performance of Wi-Fi communication.




In the LSP 500 PRO iPad app, the SSID of the current Wi-Fi network is now visible in the tab bar. So you can easily check if you are still in your chosen Wi-Fi network after having left its scope and returning.



In case there should be no Wi-Fi available, you will also see a visual indicator in the tab bar.

USB player

The handling of the built-in USB player and recorder has been further optimised. When an USB storage device is plugged in and the shortcut symbol appears, you can directly enter the player/recorder screen by pressing the USB jog-dial.




Following further features of the USB player have been enhanced:

- As an USB storage device can be used for recording, the screen also opens if there are no files on the USB storage device.
- If you press back within the first five seconds of a song being played, the previous song is played.
- If you press back after the first five seconds of a song being played, the same song is played from the beginning.

Mixing Panel

To further simplify the iPad app's usability, the name of the box is visible for each channel in the mixing panel display. Thereby you can easily identify all inputs for each of the loudspeakers.



Further enhancements of the Firmware Version 1.6.1 are:

- The SSID scan has been significantly accelerated.
- Wi-Fi networks that are not accessible are directly marked in the SSID list.
- Bluetooth firmware and Bluetooth connectivity have been improved.



To download the Firmware Update, please click [here](#).

In the Release Note, you will find a complete description of all changes and a manual on how to update the Firmware.